


<b>Search Notes</b>  	<b>Application/Control No.</b>  10771083	<b>Applicant(s)/Patent Under Reexamination</b>  HOFMEISTER ET AL.
	<b>Examiner</b>  TOAN M LE	<b>Art Unit</b>  2863

SEARCHED			
Class	Subclass	Date	Examiner
702	120,85,104,108,117	3/19/08	TL
372	26,29.021,38.1,38.02,50	3/19/08	TL
257	688	3/19/08	TL
385	92,93	3/19/08	TL
398	135,182,186	3/19/08	TL
438	13,79,82	6/9/08	TL

SEARCH NOTES			
Search Notes		Date	Examiner
702/120,85,104,108,117; 372/26,29.021,38.1,38.02,50; 257/688; 385/92,93; 398/135,182,186 (Transceiver Laser Diode Driver VCSEL)		3/19/08	TL
Transceiver Laser Diode Driver VCSEL Reference Characteristic Switch Bias Spline		3/19/08	TL
East- See Search History Printout		3/19/08	TL
438/13,79,82 (VCSEL Spline)		6/9/08	TL
East- See Search History Printout		6/9/08	TL

INTERFERENCE SEARCH			
Class	Subclass	Date	Examiner
702	120	3/19/08	TL
398	135	3/19/08	TL